



Pre and Post Satellite Images showing Flash Flood affected areas Rasuwagadhi and Surroundings, Nepal

CHARTER CALL NO :1209 For official use

Pre-image Catosat-3 MX Image of 17.04.2025



Post-Image Cartosat-2S Image of 28.08.2026




0 0.05 0.1 0.2
Kilometers

Interpretation

* A Massive flash flood in Lhende Khola (tributary of Bhote Koshi River) around 09:00 AM NPT on 26 August 2026, affected downstream areas of Trishuli River in Rasuwa, Dhading, Nuwakot, Gorkha and Chitwan districts,

* Pre & Post event Satellite images depicts the surroundings of Rasuwagadhi & surroundings where all the buidlings & Roads, bridges and other infrastrcture is washed away. Flash flood also caused the washing away of Friendship bridge. The locations can be observed for its damage at 'A', 'B', 'C' points in the map above.



Disaster Management Support Group
National Remote Sensing Centre, ISRO
Dept. of Space, Govt. of India
Hyderabad- 500 037
E-Mail: flood@nrsc.gov.in
www.nrsc.gov.in

Date of Issue 29.08.2026