

Pre and Post Satellite Images showing Flash Flood affected areas in parts of Rasuwa District, Nepal


Location Diagram



Cartographic Information

Local Projection : WGS 1984 UTM Zone 43N Datum : WGS1984
Geographic projection : Lat / Lon (DMS), Datum:WGS 84

Scale : 1:32,513



Interpretation

A Massive flash flood in Lhende Khola (tributary of Bhote Koshi River) around 09:00 AM NPT on 26 August 2026, affecting downstream areas of Rasuwa, Dhading, Nuwakot, Gorkha and Chitwan districts, Nepal. Flash flood triggered by massive debris has caused severe loss of life and damages to infrastructure. (Source : Newsmedia)

Data Source

Pre Event Image : Resourcesat-2A AWiFS, 04th April 2026
Post Event : Resourcesat-2A AWiFS, 26th August 2026

Frame Work

The best effort rapid mapping product is elaborated within a very short time frame, optimizing the available material, and has been quality checked as per NRSC/ISRO procedures. All geographical information has limitations due to scale, resolution, date and interpretation of the original source material. No liability concerning the content or the use thereof is assured by the producer.

Note: When publishing this map as part of any report, source may be indicated as ' NRSC (2026) - Pre and Post Satellite Images showing Flood affected areas in parts of Rasuwa District, Nepal (as on 26.08.2026)' , Map no : 2026/FL/NEPAL/5/26082026, NRSC/ISRO, Hyderabad.

E-mail: flood@nrsc.gov.in

