15 Feb 2022

TROPICAL CYCLONE BATSIRAI-22, PRELIMINARY SATELLITE-DERIVED ROAD DAMAGE ASSESSMENT,

Route 1 : Farafangana – Vondrozo District, Atsimo Atsinanana Province Route 2 : Midongy Atsimo – Befotoka District, Atsimo Atsinanana Province

Status: Inundated and damaged roads observed

 $\mathbf{\tilde{s}}$ Further action(s): Continue monitoring










MADAGASCAR

MADAGASCAR





District boundary

Region boundary




ROUTE 1- FARAFANGANA TOWN, FARAFANGANA DISTRICT, ATSIMO ATSINANANA REGION

Image center: 47°49'48.881"E 22°48'57.013"S



Affected road




ESRI Basemap

ROUTE 1- FARAFANGANA TOWN, FARAFANGANA DISTRICT, ATSIMO ATSINANANA REGION

Image center: 47°49'35.746"E 22°48'34.239"S



Affected road



ESRI Basemap

ROUTE 1- FARAFANGANA TOWN, FARAFANGANA DISTRICT, ATSIMO ATSINANANA REGION

Image center: 47°49'49.443"E 22°50'1.285"S



No visible damaged road




ROUTE 1- FARAFANGANA DISTRICT, ATSIMO ATSINANANA REGION

Potentially inundated road observed

Image center: 47°31'33.854"E 22°48'46.5"S







Google Earth / May 2019

Potentially damaged bridge and road

Image center: 47°28'52.345"E 22°49'6.553"S







ESRI Basemap/GeoEye-1 /5 Aug 2020

Image center: 47°28'4.198"E 22°49'18.344"S





Potentially road affected




ESRI Basemap/ WorldView-3 /10 Aug 2020

Potentially road affected

Image center: 47°24'53.552"E 22°49'4.396"S







ESRI Basemap/ WorldView-3 /10 Aug 2020

Image center: 47°20'14.486"E 22°49'5.128"S





No damage observed




Image center: 47°7'56.641"E 23°29'22.509"S



UNOSAT

Damaged road



ESRI Basemap/GeoEye-1 /16 Aug 2020

Image center: 47°7'46.894"E 23°29'39.919"S





Potentially road obstacles



ESRI Basemap/GeoEye-1 /16 Aug 2020

ROUTE 2- MIDONGY TOWN, MIDONGY-ATSIMO DISTRICT, ATSIMO ATSINANANA REGION

Image center: 47°0'57.337"E 23°35'22.739"S



Inundated town and roads



ESRI Basemap/GeoEye-1 /16 Aug 2020


Sentinel-2 / 9 Feb 2022

Image center: 47°0'40.161"E 23°39'30.73"S



UNOSAT

Inundated road



ESRI Basemap/GeoEye-1 /16 Aug 2020


Sentinel-2 / 9 Feb 2022

Image center: 47°2'0.412"E 23°43'23.283"S





No visible damaged road



ROUTE 2- BEFOTAKA VILLAGE, BEFOTAKA DISTRICT, ATSIMO ATSINANANA REGION

Image center: 46°59'15.445"E 23°49'22.932"S



No visible damaged road



ESRI Basemap/GeoEye-1 /16 Aug 2020



Route 1 : Farafangana – Vondrozo District, Atsimo Atsinanana Province

- Affected roads in Farafangana Town observed as of 15 Feb 2022;
- Potentially damaged road and standing waters observed in Vondrozo district as of 15 Feb 2022;
- Potentially damaged bridge observed in Vondrozo district as of 15 Feb 2022;

Route-2: Midongy Atsimo – Befotoka District, Atsimo Atsinanana Province

- Inundated road observed in Midongy town, Midongy Atsimo district as of 9 Feb 2022;
- Damaged road observed in Midongy Atsimo district as of 9 Feb 2022;
- No visible damaged road observed in Befotaka Village, Befotaka District, Atsimo Atsinanana Region as of 15 Feb 2022;

COPYRIGHTS AND SOURCES



Data sources:

(1) Satellite Image (Post-event)

Satellite : Pleiades Imagery Date : 15 February 2022 Resolution : 50 cm Copyright : ©CNES (2022), distribution Airbus D&S Source : Airbus DS

Satellite : Sentinel-2 Imagery Date : 9 February 2022 Resolution : 10 cm Copyright : Contains modified Copernicus Sentinel data [2022] Source: ESA

(2) Satellite Image (Pre-event)

Google Earth ESRI based map

(3) Ancillary data

Administrative boundaries: Madagascar National Disaster Manag ement Office (BNGRC)

Analysis: United Nations Satellite Centre (UNOSAT) Production: United Nations Satellite Centre (UNOSAT)





UNOSAT, United Nations Institute for Training and Research (UNITAR)7 bis, Avenue de la Paix, CH-1202 Geneva 2, Switzerland

T +41 22 917 4720 E unosat@unitar.org www.unosat.org