Analysis Results for Possible slope failure area

2016.4.18 Mon

Miura Laboratory @ Yamaguchi University













Possible slope failure area due to earthquake, April 15, Japan (No.1)







Location Map

Minamiaso village, Aso gun in Kumamoto Prefecture

∼ Near by Asoohtsu golf clob∼

Data

After event : RapidEye(2016/4/17) Before event : RapidEye(2016/3/15)

Explanation

Red color frame shows the location where slope failure possible occurred.

There are three possible slope failure area in after event image.









Sentinel Asia

Possible slope failure area due to earthquake, April 15, Japan (No.2)





Location Map

Minamiaso village, Aso gun in Kumamoto Prefecture ~Near by Tateno post office~

Data

After event : RapidEye(2016/4/17) Before event: RapidEye(2016/3/15)

Explanation

Red color frame shows the location where slope failure possible occurred.

There are three possible slope failure area in after event image.









Sentinel Asia

